

We cover  
credibility 

QSCert, spol. s r. o.  
Certification Body of Management Systems  
Residence address: Klimentka 1746/52, Nove Mesto, 110 00 Prague 1, Czech Republic  
Postal address: E. P. Voljanského 1, 960 01 Zvolen, Slovak Republic

by this

# CERTIFICATE

certifies that the Quality Management System of

**Blachprofil 2 Sp. z o.o.**

ul. Nadwiślańska 11/139; 30-527 Kraków

has been established and duly implemented  
and company applies it in accordance  
with the standard



**ISO 9001:2015**

provisions for the following areas:

**Production and sale of steel roof covering with roof accessories.**

Certified locations: 32-566 Alwernia, Grojec, ul. Grojecka 39, Poland  
41-303 Dąbrowa Górnicza, ul. Budowlanych 10, Poland

On the basis of certification audit, protocol No. PL 144/2017 it was proven that the management system meets the requirements of the above listed standard.

Certificate No.: Q – 8686/18  
Initial certification date: 14.02.2017  
Date of issue: 18.03.2018  
Expiry date: 13.02.2020


By issuing this certificate the validity of certificate Nr. Q-8686/17 of 14.02.2017 is cancelled.



**S 3177**

This certificate is valid only if it is published  
among valid certificates on [www.qscert.com](http://www.qscert.com)

Ing. Marcel Śluch  
chief executive





We cover  
credibility 

QSCert, spol. s r. o.  
Certification Body of Management Systems  
Residence address: Klimentka 52, Nove Mesto, 110 00 Prague 1, Czech Republic  
Postal address: E. P. Voljanskeho 1, 960 01 Zvolen, Slovak Republic

prin acest

# CERTIFICAT

confirma faptul ca Sistemul de Management al Calitatii la

**Blachprofil 2 Sp. z o.o.**

ul. Nadwiślańska 11/139; 30-527 Kraków

a fost stabilit si implementat in mod corespunzator,  
iar organizatia il aplica  
in conformitate cu standardul

**ISO 9001:2015**

pentru urmatoarele domenii de activitate:



**Productie si comercializare de tigla metalica si accesorii pentru acoperis.**

Locatii certificate: 32-566 Alwernia, Grojec, ul. Grojecka 39  
41-303 Dąbrowa Górnicza, ul. Budowlanych 10

Pe baza auditului de certificare, Raport de Audit Nr. PL 144/2017, s-a dovedit ca sistemul de management indeplineste cerintele standardului mentionat mai sus.

Numar certificat: Q – 8686/18  
Data certificarii initiale: 14.02.2017  
Data emiterii: 18.03.2018  
Data expirarii: 13.02.2020


Prin emiterea acestui certificat, certificatul Nr. Q - 8686/17 din data de 14.02.2017 este anulat.



**S 3177**

Acest certificat este valabil doar in  
cazul publicarii acestuia pe [www.qscert.com](http://www.qscert.com)

Ing. Marcel Sluch  
Chief executive





We cover  
credibility 

QSCert, spol. s r. o.  
Jednostka certyfikująca Systemy Zarządzania  
Adres siedziby: Klimentaska 1746/52, Nove Mesto, 110 00 Prague 1, Czechy  
Adres pocztowy: E. P. Voljanského 1, 960 01 Zvolen, Slovacka

niniejszy

# CERTYFIKAT

zaświadcza, że System Zarządzania Jakością w firmie

## Blachprofil 2 Sp. z o.o.

ul. Nadwiślańska 11/139; 30-527 Kraków

został ustanowiony i należycie wdrożony,  
a firma stosuje go zgodnie ze standardem



## ISO 9001:2015

obejmującym następujący zakres:

### Produkcja i sprzedaż stalowych pokryć dachowych wraz z akcesoriami dachowymi

Certyfikowane lokalizacje: 32-566 Alwernia, Grojec, ul. Grojecka 39, Polska  
41-303 Dąbrowa Górnicza, ul. Budowlanych 10, Polska

Na podstawie audytu certyfikacyjnego, protokół nr PL 144/2017 udowodniono, że system zarządzania spełnia wymagania wyżej wymienionej normy.

Certyfikat nr.: Q – 8686/18  
Data pierwszej certyfikacji: 14.02.2017  
Data wydania: 18.03.2018  
Data ważności: 13.02.2020  
Wydając ten certyfikat, traci ważność certyfikat nr. Q – 8686/17 z 14.02.2017 r.



**S 3177**

Certyfikat jest ważny tylko wtedy, gdy jest publikowany wśród ważnych certyfikatów na stronie [www.qscert.com](http://www.qscert.com) inż. Marcel Śluch  
Dyrektor

